


## 4.4 Detailing



### 1. Level of detail (LOD)

The level of detailing of the specific model content (End-types, drillings, connector axes and MEP axes) is controlled via those checkboxes. LOD settings need to be defined in collaboration with requester/receiver of IFC file considering the capabilities of their BIM software.

Tip:

Make sure that only the required model content and level of detail is exported.

### 2. Geometry with implicit method

You can find a more detailed explanation of the "Export geometries with implicit method (BETA)" option in the [Geometry](#) chapter.