


1.6 Keypad options

Keyboard shortcuts:

Keyboard options can be found under "Help" ? "Keyboard help":




- | | |
|--------------------------------|--------------------------------------|
| 0 Auxilliary lines | M Middlepoint |
| 1 | N Select elements by name or GUID |
| 2 cadwork 2d to Clipboard | O Measure |
| 3 rotate around Z 90 degrees | P Parallel Dimension |
| 4 rotate 2P | Q Select connected base/roof |
| 5 move | R rotation um Z |
| 6 copy | CTRL+R Rotation Allgemein |
| 7 stretch | S Helpline according segment or edge |
| 8 zoom on active point | T Text |
| 9 last selection | U activ elements invisible |
| | V Vertical dimension vertical |
| A Edgeline | W Wireline view |
| Angle dimension (wood user) | X Auxilliary line according X |
| B Beam | Y Auxilliary line according Y |
| C cut parametric | Z Altitude dimension |
| D merge line | Auxilliary line according Z |
| E Auxiliary line with distance | |
| F Add surface | < Zoom all |
| G Heightline | Ctrl Alt : activate polygon |
| H Horizontal dimension | Ctrl+B Open BIMteam upload |
| I inactiv elements invisible | |
| J all elements visible | Shift ← → move X |
| K node | Shift ↑ ↓ move Y |
| L Linie | Ctrl ↑ ↓ move Z |

Many keyboard shortcuts can be combined with other letters. These are listed at the bottom in the comment bar.



Function keys:

The function keys can be defined under "Help" ? "Definition F-keys":



In the function key settings, it is possible to assign a new function to a key by clicking on "Edit".